

Nx Talkshow Systems – Nx12, Nx6, iQ6

Version 1.4.0r

(11 June 2010)

- Corrected missing ‘to caller’ audio when the first caller of a large conference drops
- Incoming calls rejected due to Busy All now return the proper cause code on ISDN
- Busy All line status is now reflected on frontpanel and webpage
- Settings backup and restore added to webpage
- Status webpage updates without refreshing
- The Setup Wizard page loads much more quickly
- Axia Element control surface correctly displays state of shared POTS lines
- Corrected behavior when two Nx systems are sharing a POTS line and both systems are also using Auto Answer to Hold
- Speakerphone mode now toggles off when switching a Desktop Director between Talent and Producer mode
- System crash logs are now sent to the syslog server, if configured

Version 1.3.0r

(30 March 2010)

- Fix for studio-to-caller audio for second studio in Single and Single (Mono out) mix modes
- Added option to disallow moving locked lines between hybrids to Tel webpage
- Filled out help pages on web interface
- Fix stack overflow in LWCP message parser
- Resolved an echo canceller malfunction
- Adjusted contrast scale for new LCDs
- Frontpanel will show line status screen even if no line cards are installed
- Fix for CID differences in some regions of Canada

Version 1.2.1r

(28 January 2010)

Please note – this list of changes is not comprehensive

- Regional ISDN fixes
- Optional caller ID start indication on Telco web page
- Fixed DTAS caller ID interpretation
- Numerous web interface fixes and changes
 - More intuitive Livewire configuration
 - Livewire GPIO support
 - Audio level monitoring
 - Line allocation and priority status now available on Setup Wizard web page
 - GPIO input source on Setup Wizard web page
 - Fixed display of POH input sources on status web page
- Fixed missing ‘to studio’ audio on second show with Single Mono mixing
- Changing show mode no longer requires reboot
- Changing show lines or priority status no longer requires reboot
- Corrected operation of “Clock on BRI loss” option
- Added redial and phone book to Desktop Director UI
- Fixed hookflash function

(Version 1.2.1r, continued)

- Added POTS line sharing between two Nx12s
- Enabled syslog support for error logging
- Added auto-answer option
- Fixed GPO 'ring in' indication
- Console controller talent/producer settings now save correctly
- Added mute and acoustic adapt commands to Assistant Producer protocol
- Fixes for Assistant Producer 'garbage characters' and 'duplicate messages'