

Telos Nx12 Release Notes

Many users inquire what features are new in the latest release. The following Release Notes show the improvements and features added with each significant release.

Release Notes:

Version 1.2.1r

Released Jan 28, 2010

Please note – this list of changes is not comprehensive

- Regional ISDN fixes
- Optional caller ID start indication on Telco web page
- Fixed DTAS caller ID interpretation
- Numerous web interface fixes and changes
 - More intuitive Livewire configuration
 - Livewire GPIO support
 - Audio level monitoring
 - Line allocation and priority status now available on Setup Wizard web page
 - GPIO input source on Setup Wizard web page
 - Fixed display of POH input sources on status web page
- Fixed missing 'to studio' audio on second show with Single Mono mixing
- Changing show mode no longer requires reboot
- Changing show lines or priority status no longer requires reboot
- Corrected operation of "Clock on BRI loss" option
- Added redial and phone book to Desktop Director UI
- Fixed hookflash function
- Added POTS line sharing between two Nx12s
- Enabled syslog support for error logging
- Added auto-answer option
- Fixed GPO 'ring in' indication
- Console controller talent/producer settings now save correctly
- Added mute and acoustic adapt commands to Assistant Producer protocol
- Fixes for Assistant Producer 'garbage characters' and 'duplicate messages'